

AMENDMENTS TO THE CLAIMS:

This listing of claims will replace all prior versions, and listings, of claims in the application:

LISTING OF CLAIMS:

1. (original) An arrangement for fitting a massage motor in a coil spring assembly of a bed, an armchair or the like, characterised in that the massage motor (3) is fitted inside the coil spring assembly; and in that said motor (3) is connected to the upper side of at least some of the springs (1) in the coil spring assembly.
2. (original) An arrangement according to Claim 1, characterised in that the massage motor (3) is fitted on the underside of an attachment plate (5) which is fastened to a number of springs (1).
3. (currently amended) An arrangement according to Claim 1 [[or 2]], characterised in that the massage motor (3) is mounted centrally in relation to the surface of the coil spring assembly, and in that a pair of springs (1) have been omitted to provide room for the massage motor (3).
4. (currently amended) An arrangement according to ~~any one of the preceding Claims~~ claim 1, characterised by movement transmission elements (6) connected to the massage motor (3) and extending out from said motor (3) to a number of springs (1), said elements (6) being connected to the springs (1) so as to transmit the movement of the motor (3) to said springs (1).

5. (original) An arrangement according to Claim 4, characterised in that the movement transmission element (6) is a strip-like element extending out from the massage motor (3).

6. (original) An arrangement according to Claim 5, characterised in that a plurality of strip-like movement transmission elements (6) are disposed to extend from the massage motor (3) to the corners of said coil spring assembly.

7. (original) An arrangement according to Claim 4, characterised in that the movement transmission element (6) is comprised of spring steel wires or rods extending out from the massage motor (3).

8. (new) An arrangement according to Claim 2, characterised in that the massage motor (3) is mounted centrally in relation to the surface of the coil spring assembly, and in that a pair of springs (1) have been omitted to provide room for the massage motor (3).